



# DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

## INSPECTION REPORT

Michael O. Leavitt Governor Ted Stewart **Executive Director** James W. Carter

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax)

Partial: X Complete:\_ Exploration:\_\_\_ Inspection Date & Time: 5/19/94 2:00 to 4:00 Pm Date of Last Inspection: 4/19/94

Division Director 801-538-5319 (TDD)			_	
Mine Name: Bear Canyon Mine County: Ex	mery Permit	Number	: ACT/015/02	<u> 25</u>
Permittee and/or Operator's Name: Co-Op Mining	Company			
Business Address: P.O. Box 1245, Huntington, Ut.				
		Dlant	Other	
Type of Mining Activity: Underground X Su	riace Prep.	Piani		
State Officials(s): Tom Munson				
Company Official(s): Marlo				
Federal Official(s): none				
Weather Conditions: clear				
Existing Acreage: Permitted-1531 Disturbed-24 Regraded Seeded Bonded-24				
Increased/Decreased: Permitted Disturbed				d
Status:Exploration/Active/Inactive/Tem	porary Cessation	/Bond	l Forfeiture	
Reclamation (Phase I/Phase II/Final				
			<i>J</i>	
REVIEW OF PERMIT, PERFORMANCE STANDARDS	& PERMIT CONDIT	TION REQ	<u>UIREMENTS</u>	
1 DEDIVING CHANGE ED MICHES DEVELO	EVALUATED	<u>N/A</u>	COMMENTS	<u>NOV/ENF</u>
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<u>[X]</u>	닏	닏	닏
2. SIGNS AND MARKERS 3. TOPSOIL	[ <u>X]</u>	ĻĻ	<u> </u>	<u> </u>
4. HYDROLOGIC BALANCE:	X	ш	<u> </u>	Ш
a. DIVERSIONS	(V)	r ı	[X]	r 1
b. SEDIMENT PONDS AND IMPOUNDMENTS	[X] [X]	납	<u>[X]</u>	H
c. OTHER SEDIMENT CONTROL MEASURES		片	1 <u>771</u>	<u> </u>
d. WATER MONITORING		计	X	7
e. EFFLUENT LIMITATIONS		Ħ	[X]	<u>i j</u>
5. EXPLOSIVES	[X] [X]	Ħ		<u> </u>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	ΪXÌ	Π	Ti	口
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENT	$S \qquad \overline{\overline{[X]}}$	口	口	$\Box$
8. NONCOAL WASTE	$\overline{[X]}$	$\overline{\Box}$	$\Box$	$\overline{\Box}$
9. PROTECTION OF FISH, WILDLIFE AND				
RELATED ENVIRONMENTAL VALUES	<u>[X]</u>			
10. SLIDES AND OTHER DAMAGE	[X]	$\Box$	$\Box$	$\Box$
11. CONTEMPORANEOUS RECLAMATION	<u>[X]</u>	Ц		Ĺ
12. BACKFILLING AND GRADING	[X]	Ц	Ĺļ	Ļļ
13. REVEGETATION	[X]	Щ	닏	ĻĻ
14. SUBSIDENCE CONTROL	[ <u>X]</u>	닏	닏	
<ul><li>15. CESSATION OF OPERATIONS</li><li>16. ROADS:</li></ul>	[X]	ш		ш
a. CONSTRUCTION/MAINTENANCE/SURFACING	(V)	r 1	r 1	ſ٦
b. DRAINAGE CONTROLS	[ <u>X]</u> [X]	Η	무	<del>[ ]</del>
17. OTHER TRANSPORTATION FACILITIES	<u> A </u> [X]		<u>_</u>	<u></u> [ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<u>[X]</u> [X]	<u> </u>	स्रि	급
	ate) $\square$	计	[ ]	ㄷ
20. AIR QUALITY PERMIT		<del>   </del>	Ħ	i i
21. BONDING & INSURANCE	[X]	$\Box$	口	口



#### **INSPECTION REPORT**

(Continuation sheet) PERMIT NUMBER: ACT/015/025 Page 2 of 2

DATE OF INSPECTION: 4/19/94

(Comments are Numbered to Correspond with Topics Listed Above)

#### 4. HYDROLOGIC BALANCE:

<u>Diversions</u> - Diversions appeared to be in good order and were in the process of being cleaned in some areas.

Sediment ponds and impoundments - The sediment pond swere functioning as designed and their was some water in pond B as it caught the overflow whern the water truck was filling.

Water monitoring - 1ST Quarter water monitoring has been received by the Division.

Effluent Limitations - UPDES reports were in order for the sediment ponds and the mine water discharge.

### 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

The Bath House construction is progressing slowly. The operator stated that the shower facility should be ready in a couple of weeks. The septic field is being installed and approval from the Dept. of Health will be required. Drainage from the upper parking lot was completed as a separate ditch and discussions with Marlo recommended a possible modification to this plan to hopefully combine the drainage from the upper and lower parking areas. It was noted that a permit amendment would be required prior to implementation.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Wendell Owen (Co-Op)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: 162 Mm #25 Date: 5/27/99